

Assembly Instructions

Female Threaded Connector / Male Threaded Connector 12 + 3

1. 25 mm
2. 4 mm
3. crimp
4. click
5. click
- 6.
7. 15/18
8. 15/18

The inner conductors (bigger cross section for middle insert) shorten appr. 2–3 mm

click

click

15/18

15/18

Shield is not allowed to touch second O-ring