

Assembly Instructions

Panel Connector

1.
2.

! x Contact ø 1 mm = max. 4 mm stripping length
Contact ø 2 mm = max. 7 mm stripping length
3.

crimp
4.

click
5.

1 x PE klick

click
6.

click